

Amendments to the Specification:

Please replace the paragraph beginning at page 6, line 17, with the following paragraph:

A first sprocket 70 is keyed at 71 to motor shaft 32 at the location of bushing 32a (Fig. 7). A second sprocket 72 is bolted at 73 to sprocket mounting plate 74, the latter being welded at 75 to rotor 52 at outer rotor surface ~~[[54]]~~ 53. A drive chain, not shown, connects sprockets 70, 72 whereupon activation of motor 31 and the sprocket chain assembly, rotor 52 rotates on bearings 50, 51. Shaft 40 is fixed in place and does not rotate. Referring to Fig. 7, drive assembly 30 includes motor 31 and the sprocket chain assembly, the latter being enclosed by walls 16, 22 and 23.